



SALT LAKE

Test Report

RI 16804 (GB) Pillow Sample Dunrich LTD

IDFL # 23-486172

Legal Label Inc.
22 May 2023

Maggie Terry
Legal Label Inc.
4 Whites Bridge Rd
Suite #275
Windham, Maine 04062
United States

mterry@legallabel.com
licensing@legallabel.com
Normal (8-10 Days)

Arrival Date: 19 May 2023
Report Date: 22 May 2023

Sample Type: Pillow
Shipped By: UPS 1Z40X9750309737931
Label: No Filling Label
Sample Identification: RI 16804 (GB)
Pillow Sample
Dunrich LTD



This analysis represents (within normal testing variances) the test results from the sample(s) submitted. The analysis may not represent the entire lot, batch or production run. In no event shall IDFL be responsible or liable for any direct, indirect, punitive, incidental, special, or consequential damages whatsoever arising out of or connected with the use of, misuse of, or reliance upon such results or analysis. This test report is subject to the Terms and Conditions found at www.idfl.com.

IDFL LABORATORY AND INSTITUTE

IDFL SALT LAKE
1455 South 1100 East
Salt Lake City, UT 84105
USA
+1 801 467 7611
info@idfl.com

IDFL EUROPE AG
Zürcherstrasse 282
CH-8500 Frauenfeld
Switzerland
+41 52 765 1574
europa@idfl.com

IDFL CHINA
Tonghui Mid-Road 688, Xiaoshan
Hangzhou Zhejiang 311200
China
+86 571 8273 6561
china@idfl.com

IDFL TAIPEI
8F, No. 312, Sec. 2
New Taipei Blvd, Xinzhuang Dist
New Taipei City, Taiwan
+886-2-8522-8790
taiwan@idfl.com

IDFL VIETNAM
No. 8, B4 Street An Loi Dong Ward
District 2, Ho Chi Minh City
Vietnam
+84 282-244-7611
vietnam@idfl.com



Approved By

www.idfl.com

Client 6663

SL

Sample 1 of 2



SALT LAKE

Test Report

RI 16804 (GB) Pillow Sample Dunrich LTD

IDFL # 23-486172

Legal Label Inc.
22 May 2023

State of Ohio Filling Inspection / Preparation

Fill Type (1)	Loose Fibers	% of Total Filling Wt.
Fiber Analysis:	polyester	100.0%
Filling or Used as Structure?	Filling	
Location of Filling / Type in product	Body	
Detailed Location:	Body	

Fiber Analysis: Quantitative AATCC 20A 2014

Fill Type (1) Loose Fibers

polyester 100.0%

This analysis represents (within normal testing variances) the test results from the sample(s) submitted. The analysis may not represent the entire lot, batch or production run. In no event shall IDFL be responsible or liable for any direct, indirect, punitive, incidental, special, or consequential damages whatsoever arising out of or connected with the use of, misuse of, or reliance upon such results or analysis. This test report is subject to the Terms and Conditions found at www.idfl.com.

IDFL LABORATORY AND INSTITUTE

IDFL SALT LAKE
1455 South 1100 East
Salt Lake City, UT 84105
USA
+1 801 467 7611
info@idfl.com

IDFL EUROPE AG
Zürcherstrasse 282
CH-8500 Frauenfeld
Switzerland
+41 52 765 1574
europe@idfl.com

IDFL CHINA
Tonghui Mid-Road 688, Xiaoshan
Hangzhou Zhejiang 311200
China
+86 571 8273 6561
china@idfl.com

IDFL TAIPEI
8F, No. 312, Sec. 2
New Taipei Blvd, Xinzhuang Dist
New Taipei City, Taiwan
+886-2-8522-8790
taiwan@idfl.com

IDFL VIETNAM
No. 8, B4 Street An Loi Dong Ward
District 2, Ho Chi Minh City
Vietnam
+84 282-244-7611
vietnam@idfl.com

Approved By

www.idfl.com

Client 6663

SL

Sample 1 of 2